

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	18	window and passivation and aluminum near4 fuse and copper and (aluminum Al) and window and damascene	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 15:01
L2	18	window and passivation and aluminum near4 fuse and copper and (aluminum Al) and window and damascene and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 15:02
L4	2170	((257/209) or (257/529) or (257/e21.592) or (257/e23.149) or (257/e23.15)).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/03 15:52
L5	51	4 and fuse and alumin\$1um and copper and ("low" adj2 dielectric low-k) and laser and passivati\$2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 15:54
S1	59	"5,879,966" "6,121,073" "6,330,252" "6,295,721" "6,335,229"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/03 12:05
S2	10	((("5,879,966") or ("6,121,073") or ("6,330,252") or ("6,295,721") or ("6,335,229"))).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 11:11
S3	0	("804713.ap.").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 11:15
S4	5	"804713".ap.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 11:15
S5	716	fuse.ti. and "257"/\$7.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 14:03

S6	24972	fuse.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 14:04
S7	0	fuse.ti. and (damage fragile crack\$3) near6 dielectric near6 laser adj trimming	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 14:06
S8	0	fuse.ti. and (damage fragile crack\$3) near12 dielectric near12 laser adj trimming	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 14:07
S9	0	fuse.ti. and (damage fragile crack\$3) near12 (passivat\$3 dielectric) near12 laser adj trimming	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 14:07
S10	2	fuse.ti. and (damage fragile crack\$3) near12 laser adj trimming	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 14:09
S11	193	fuse.ti. and (damage fragile crack\$3) and (passivat\$3 dielectric) and semiconductor adj device	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 14:26
S12	836	(257/529).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 14:26
S13	757	(257/529).CCLS.	US-PGPUB; USPAT	OR	OFF	2005/07/06 14:26
S14	96	S13 and crack\$3 and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 14:27
S15	757	(257/529).CCLS.	US-PGPUB; USPAT	OR	OFF	2005/07/06 15:52
S16	32	S15 and crack\$3 and laser and (silicon adj dioxide "Si O.sub.2")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 16:23

S17	2	("6433406").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/06 16:23
S18	34	(US-20050110070-\$ or US-20050101114-\$ or US-20050077594-\$ or US-20050077593-\$ or US-20040119138-\$ or US-20030168714-\$ or US-20030160297-\$ or US-20030153173-\$ or US-20030153135-\$ or US-20030151060-\$ or US-20030139028-\$ or US-20030132504-\$ or US-20030119227-\$ or US-20030011042-\$ or US-20020135043-\$).did. or (US-6335229-\$ or US-6330252-\$ or US-6295721-\$ or US-6121073-\$ or US-5879966-\$ or US-5844296-\$ or US-6750129-\$ or US-6518643-\$ or US-6300232-\$ or US-5955773-\$ or US-6104079-\$ or US-6268638-\$ or US-6288437-\$ or US-6433406-\$).did. or (US-6335229-\$ or US-6295721-\$ or US-6121073-\$ or US-5879966-\$ or JP-11017676-\$).did.	US-PGPUB; USPAT; DERWENT	OR	OFF	2005/07/06 16:47
S19	3	S18 and copper near4 wiring and aluminum near4 fuse	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:48
S20	3	S18 and copper near4 wiring and aluminum near4 fuse	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:53
S21	28393	fuse.ti. copper near4 wiring and aluminum near4 fuse	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:53
S22	28354	fuse.ti. (copper near2 wiring near10 aluminum near2 fuse)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:53

S23	4	fuse.ti. and (copper near2 wiring near10 alumin\$um near2 fuse)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:55
S24	0	jp-02068360\$-\$\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:56
S25	0	jp-0268360\$-\$\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:56
S26	2	jp-2001093981\$-\$\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/06 16:56
S27	2	("6433406").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 13:18
S28	0	S27 and etch adj stop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 10:40
S29	1	S27 and etch\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 10:44
S30	1074	etch adj stop.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 10:44
S31	248	etch adj stop.ti. and "257"/\$7.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 10:51
S32	248	etch adj stop.ti. and "257"/\$7.ccls. and etch adj stop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 10:59

S33	5	"232214".ap.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 11:14
S34	112	etch adj stop and fuse.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 11:48
S35	112	etch adj stop and fuse.ti. and fuse	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 11:49
S36	0	titankum adj nitride near3 etch adj stop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 13:18
S37	54	titanium adj nitride near3 etch adj stop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 13:18
S38	6	"6433406"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 13:46
S39	2	("6433406").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 13:46
S40	1	S39 and barrier	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 13:46
S41	10	(US-6335229-\$ or US-6330252-\$ or US-6295721-\$ or US-6121073-\$ or US-5879966-\$).did. or (US-6335229-\$ or US-6295721-\$ or JP-11017676-\$ or US-6121073-\$ or US-5879966-\$). did.	USPAT; DERWENT	OR	OFF	2005/07/07 14:28
S42	6	S41 and (thick thickness)	USPAT; DERWENT	OR	OFF	2005/07/07 14:29
S43	6	S41 and (thick thickness)	USPAT; DERWENT	OR	ON	2005/07/07 14:39

S44	0	S41 and (thick thickness) near6 guard adj ring	USPAT; DERWENT	OR	ON	2005/07/07 14:31
S45	4	(guard adj ring guard-ring) near10 (thick thickness) and fuse.ti.	USPAT; DERWENT	OR	ON	2005/07/07 14:44
S46	8	(guard adj ring guard-ring) near20 (thick thickness) and fuse.ti,ab.	USPAT; DERWENT	OR	ON	2005/07/07 15:51
S47	2	("5795819").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/07 15:52
S48	10	(US-6335229-\$ or US-6330252-\$ or US-6295721-\$ or US-6121073-\$ or US-5879966-\$).did. or (US-6335229-\$ or US-6295721-\$ or JP-11017676-\$ or US-6121073-\$ or US-5879966-\$). did.	USPAT; DERWENT	OR	OFF	2005/07/07 17:19
S49	47702	"10" and laser near6 wavelength	USPAT; DERWENT	OR	OFF	2005/07/07 17:19
S50	2	S48 and laser near6 wavelength	USPAT; DERWENT	OR	OFF	2005/07/07 17:20
S51	14	guard adj ring near6 barrier and fuse.ti,ab,clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 09:03
S52	14	guard adj ring near6 barrier and fuse.ti,ab,clm. and barrier and guard adj ring	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 09:05
S53	3	guard adj ring near6 barrier and fuse.ti,ab,clm. and barrier and guard adj ring near6 etch adj stop and barrier and guard adj ring and etch adj stop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 09:05
S54	67	ying.in. and fuse and window	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 09:19
S55	8	ying.in. and fuse and window and passivation	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 10:08

S56	670	teos.ti,ab,clm. and dielectric adj constant	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 10:09
S57	362	teos.ti,ab,clm. and dielectric adj constant near6 "low"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 10:10
S58	342	teos.ti,ab,clm. and dielectric adj constant near2 "low"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 10:11
S59	236	teos.ti,ab,clm. and dielectric adj constant near2 "high"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 10:11
S60	90	S58 and S59	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 10:11

S61	37	(US-20020135043-\$ or US-20030011042-\$ or US-20030119227-\$ or US-20030132504-\$ or US-20030139028-\$ or US-20030151060-\$ or US-20030153135-\$ or US-20030153173-\$ or US-20030160297-\$ or US-20030168714-\$ or US-20040119138-\$ or US-20050077593-\$ or US-20050077594-\$ or US-20050101114-\$ or US-20050110070-\$).did. or (US-5844296-\$ or US-5879966-\$ or US-5955773-\$ or US-6104079-\$ or US-6121073-\$ or US-6268638-\$ or US-6288437-\$ or US-6295721-\$ or US-6300232-\$ or US-6330252-\$ or US-6335229-\$ or US-6433406-\$ or US-6518643-\$ or US-6750129-\$ or US-6300252-\$).did. or (JP-2001093981-\$).did. or (JP-11017676-\$ or US-5879966-\$ or US-6121073-\$ or JP-2001093981-\$ or US-6295721-\$ or US-6335229-\$). did.	US-PGPUB; USPAT; JPO; DERWENT	OR	OFF	2005/07/08 11:01
S62	2	S61 and kagiwata.in.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/08 11:01
S63	0	kagiwata.in. and fuse and guard adj ring	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/08 11:02
S64	7	kagiwata.in. and fuse	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/08 11:21
S65	1714	((257/209) or (257/529) or (257/E21.592) or (257/E23.149) or (257/E23.15)).CCLS.	US-PGPUB; USPAT	OR	OFF	2005/07/08 11:22
S66	73	S65 AND LASER NEAR2 (MELTING TRIMMING) AND (CRACK\$3 DAMAG\$3 MOISTURE) AND FUSE	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/08 11:24

S67	6	"804713".ap.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 14:03
S69	2	("6433406").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 20:26
S70	2	("6300252").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 19:56
S71	2	jp-2001093981\$-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 21:38
S72	41	"low" near3 (k dielectric permittivity) near10 fuse.ti,ab,clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/02 21:38
S73	16	"low" near3 (k dielectric permittivity) near3 fuse.ti,ab,clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/02 21:40
S74	16	"low" near3 (k dielectric permittivity) near3 fuse.ti,ab,clm. and (dielectric permittivity)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/02 22:08
S75	299	dielectric adj constant near6 TEOS	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/02 22:08
S76	29	"low" near2 (dielectric adj constant) near2 TEOS	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/02 22:09
S77	1	(US-20050205965-\$).did.	US-PGPUB	OR	OFF	2006/01/02 22:34
S78	5	"6330252"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 22:37

S79	11	"6300252"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 23:02
S80	10	"6300252" and passivat\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 23:03
S81	2	"6300252".pn. and passivat\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 23:29
S82	101	damascene near6 fuse	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 23:29
S83	57	damascene near6 fuse.ti,ab,clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 23:29
S84	57	damascene near6 fuse.ti,ab,clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/02 23:30
S85	20	dual adj damascene near6 fuse.ti, ab,clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 00:07
S86	2	("6440833").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/02 23:43

S87	107	(US-20020017704-\$ or US-20020060352-\$ or US-20020084526-\$ or US-20020096735-\$ or US-20020113297-\$ or US-20020135043-\$ or US-20020145176-\$ or US-20020145177-\$ or US-20020158052-\$ or US-20020170898-\$ or US-20020171119-\$ or US-20020179990-\$ or US-20030011042-\$ or US-20030119227-\$ or US-20030132504-\$ or US-20030139028-\$ or US-20030151060-\$ or US-20030153135-\$ or US-20030153173-\$ or US-20030155629-\$ or US-20030160297-\$ or US-20030168714-\$ or US-20030213998-\$ or US-20040012071-\$ or US-20040032030-\$ or US-20040080022-\$).did. or (US-20040096591-\$ or US-20040115875-\$ or US-20040119138-\$ or US-20040183155-\$ or US-20040195648-\$ or US-20050077593-\$ or US-20050077594-\$ or US-20050101114-\$ or US-20050110070-\$ or US-20050205965-\$).did. or (US-4210875-\$ or US-4238839-\$ or US-4602420-\$ or US-4774561-\$ or US-4796075-\$ or US-4827325-\$ or US-4870472-\$ or US-5241212-\$ or US-5303402-\$ or US-5493148-\$ or US-5567643-\$ or US-5578517-\$ or US-5578861-\$ or US-5729041-\$ or US-5757060-\$ or US-5757264-\$ or US-5844295-\$ or US-5844296-\$ or US-5879966-\$ or US-5888851-\$ or US-5955773-\$ or US-5965927-\$ or US-5972756-\$ or US-6104079-\$ or US-6121073-\$ or US-6160302-\$).did. or (US-6177714-\$ or US-6180503-\$ or US-6180992-\$ or US-6255671-\$ or US-6268638-\$ or US-6274410-\$ or US-6288437-\$ or US-6294474-\$ or US-6295721-\$ or US-6300232-\$ or US-6300252-\$ or US-6320242-\$ or US-6320769-\$ or US-6330252-\$ or US-6351295-\$ or US-6352506-\$ or US-6380838-\$ or US-6420772-\$	US-PGPUB; USPAT; JPO; DERWENT	OR	OFF	2006/01/03 07:55
-----	-----	--	--	----	-----	------------------

S88	14	S87 and etch adj stop adj (layer film)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/03 07:56
S89	14	S87 and etch adj stop adj (layer film)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 07:56
S90	153	fuse near4 passivation adj layer	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/03 09:21
S91	246	fuse near4 (passivation adj layer)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/03 09:21
S92	179	fuse near4 (passivation adj layer). ti,ab,clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:21
S93	51	fuse near4 (passivation adj layer). ti,ab,clm. and copper and aluminum	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:21
S94	9	fuse near4 (passivation adj layer). ti,ab,clm. and copper and aluminum and (low-k ("low" near1 dielectric))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:37
S95	0	shimooka.in. and S87	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 09:38
S96	2	jp-11224900\$-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 15:52
S97	2	"5677556".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 11:16

S98	4	fuse.ti,ab,clm. and window and passivation near4 (silicon adj dioxide) and aluminum near4 fuse and copper and damascene and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:39
S99	4	fuse.ti,ab,clm. and window and passivation near4 (silicon adj dioxide) and aluminum near4 fuse and copper and damascene	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:39
S100	18	fuse.ti,ab,clm. and window and passivation and aluminum near4 fuse and copper and damascene	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:40
S101	18	fuse.ti,ab,clm. and window and passivation and aluminum near4 fuse and copper and damascene and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:50
S102	1	aluminum near1 fuse.ti,ab,clm. and window and passivation and aluminum near4 fuse and copper and damascene and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:50
S103	3	aluminum near1 fuse and window and passivation and aluminum near4 fuse and copper and damascene and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:51
S104	3	aluminum near1 fuse and window and passivation and aluminum near4 fuse and copper and damascene and laser and (aluminum Al)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 12:53
S105	7	aluminum near1 fuse and window and passivation and aluminum near4 fuse and copper and (aluminum Al)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 13:07
S106	30	window and passivation and aluminum near4 fuse and copper and (aluminum Al)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 13:44
S107	30	window and passivation and aluminum near4 fuse and copper and (aluminum Al) and window	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/01/03 14:55